SAMPLE DELIVERY GROUP	CLIENT SAMPLE ID	RESULT	DATE SAMPLED	TIME COLLECTED
Pine Bush	Pine Bush HS GN Bathroom o/s022	1.94	10/07/2021	04:30
Pine Bush	Pine Bush Hs 2nd Floor woman's BR o/s 2B sink #3	1.43	10/07/2021	04:50
Pine Bush	Pine Buhs Crispell Middle KItchen- Dishwashing Sink	6.63	10/07/2021	05:02
Pine Bush	Pine Bush EJR Phys Ed. 132 Coaches BR	1.99	10/07/2021	05:04
Pine Bush	Pine Bush EJR Rm 1 CS	58.1	10/07/2021	05:06
Pine Bush	Pine Bush EJR Rm 5 CS	48.1	10/07/2021	05:08
Pine Bush	Pine Bush EJR Rm 12 CS	26.1	10/07/2021	05:09
Pine Bush	Pine Bush EJR Rm 116CS	5.77	10/07/2021	05:13
Pine Bush	Pine Bush EJR BF o/s Cafe	ND<1.00	10/07/2021	05:14
Pine Bush	Pine Bush EJR Rm 22 CS	5.78	10/07/2021	05:15
Pine Bush	Pine Bush EJR Rm 27 CS	1.65	10/07/2021	05:17
Pine Bush	Pine Bush HS Rm 142 CS Center	ND<1.00	10/07/2021	04:35
Pine Bush	Pine Bush Pak Rm 103 CS	ND<1.00	10/07/2021	05:57
Pine Bush	Pine Bush CVMS Main Office B114 Sink	6.21	10/07/2021	05:45
Pine Bush	Pine Bush CVMS Rm 24 CS Right #2	18.3	10/07/2021	05:50
Pine Bush	Pine Bush CVMS Kitchen Dishwash Sink Right	96.5	10/07/2021	05:47
Pine Bush	Pne Bush CVMS Rm A27 CS Left #1	13.9	10/07/2021	05:51
Pine Bush	Pne Bush CVMS Rm 24 CS Left #1	46.1	10/07/2021	05:50
Pine Bush	Pine BUsh CES Rm 230 CS	2.46	10/07/2021	05:36
Pine Bush	Pine Bush HS Rm 116 Sink- Athletic Trainer	1.11	10/07/2021	04:31
Pine Bush	Pine Bush HSMain Office- VP Bathroom Sink	1.04	10/07/2021	04:37
Pine Bush	Pine Bush HSMain Office- Princ. Bathrrom Sink	ND<1.00	10/07/2021	04:38
Pine Bush	Pine Bush HS Rm 4 CS Back Side Center (Right)	ND<1.00	10/07/2021	04:39
Pine Bush	Pine Bush HS Rm 166 Prep Sink	2.54	10/07/2021	04:47
Pine Bush	Pine Bush HS Rm 166 CS side of island #1	1.31	10/07/2021	04:48
Pine Bush	Pine Bush HS Rm 166 CS Front side of Isalnd #2	4.14	10/07/2021	04:48